

ADEQ Hazardous Waste Division Technical Branch Trip Report

Project	Cedar Chemical Site
Location	Helena-West Helena
Date	4/27/2012
Time	1100 to 1136 hours
Reason	Monthly Site Visit
ADEQ personnel	Annette Cusher Jim Rigg
Facility, contractor and EPA personnel	Mr. Harrington
Activity Summary	<p>Jim and I were met upon arrival at the site by Mr. Harrington. The following issues were discussed during the walk through.</p> <ul style="list-style-type: none"> • A pole was removed cracking the asphalt while demolishing a shed. The remaining poles were cut off at the level of the asphalt. • The old lab building is collecting water after rain events and has become moldy. Harcross would like to demolish the building. • The waste from the renovation of the sump is still covered on a slab. Mr. Harrington indicated Harcross was in contact with Clean Harbors for disposal. • Mr. Harrington also indicated that Harcross would be running underground utilities when they begin to utilize the unused unit. • There are several five gallon buckets of what appears to be purge water (buckets are labeled with monitoring well numbers) still on-site. Harcross would like to know what should be done with the containers. • There is a desk and files being moved into the warehouse. • Harcross is planning on placing fresh gravel in the boneyard and placing the “loose” equipment into the boneyard to improve the look of the site. • There are some empty, damaged containers in a area of the site. Harcross indicated that Enviro Tech has been told to properly dispose if the waste containers.



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:	Cedar Chemical Site							
Photographer:	A. Cusher				Witness:	J. Rigg		
Photo #	1	Of	6		Date:	4/27/2012	Time:	
Description:	Cracked asphalt from pole removal							



Photographer:	A. Cusher				Witness:	J. Rigg		
Photo #	2	Of	6		Date:	4/27/2012	Time:	
Description:	Area where poles were cut off at asphalt level							



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:	Cedar Chemical Site						
Photographer:	A. Cusher			Witness:	J. Rigg		
Photo #	3	Of	6	Date:	4/27/2012	Time:	
Description:	Covered waste pile						



Photographer:	A. Cusher			Witness:	J. Rigg		
Photo #	4	Of	6	Date:	4/27/2012	Time:	
Description:	5 gallon containers of purge water						



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:	Cedar Chemical Site					
Photographer:	A. Cusher			Witness:	J. Rigg	
Photo #	5	Of	6	Date:	4/27/2012	Time:
Description:	Close up of 5 gallon container label					



Photographer:	A. Cusher			Witness:	J. Rigg	
Photo #	6	Of	6	Date:	4/27/2012	Time:
Description:	Damaged empty containers					

